

## Release Note

**Product Name:** VM-2DT

<b>Current Version:</b>	Ver.Type	Ver No.	Date
	Firmware	4.0.40281	August 2017
	Software	–	–
	Web	–	–
	Hardware	–	–

**RN Date:** August 2017

**Reference:** 12886

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VM-2DT	Any	Yes	N/A

### Technical Notes:

- New signal output option.
- Fixed various cases where switching or power-up sometimes affected output signal quality.
- Fixed other bugs.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note

**Product Name:** VM-2DT

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	4.0.40281	August 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** August 2017

**Reference:** 12886

### Modifications:

QC ID	Modification Description
10073	New option to cease signal output when no input is connected

### Bugs Fixed:

QC ID	Fixed Bug Description
9790	Device Sn of 14 digits is supported
9791, 9797, 9824, 9837, 9956, 10060, 10065, 10069, 10071, 9956, 10071, 10929, 11692	Fixing various cases where switching or power-up sometimes affected output signal quality
9813	Help list presentation fixed



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
9820	Unit may reach high temperature, though well within supported temperature range, after full day of work at high traffic load

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
10069	Input switching cause ~6-7sec video output signal delay and audio heard before video display

**Preceding Version:** F: 2\_31.00.3\_ID



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note History

**Product Name:** VM-2DT

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	2_31.00.3_ID	April 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** April 2017

**Reference:** 12247

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VM-2DT	Any	Yes	N/A

**Technical Notes:**

- This is a release note for a new product.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note History

**Product Name:** VM-2DT

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	2_31.00.3_ID	April 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** April 2017

**Reference:** 12247

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/downloads/VM-2DT>

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
10069	Input switching cause ~6-7sec video output signal delay and audio heard before video display

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)