

## Release Notes

**Product Name:** VP-426H2

**Current Version:**

| Ver.Type | Ver No. | Date      |
|----------|---------|-----------|
| Firmware | 1.07    | July 2018 |
| Software | –       | –         |
| Web      | –       | –         |
| Hardware | –       | –         |

**RN Date:** July 2018

**Reference:** 14151

### Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| VP-426H2     | Any                            | Yes                       | Yes                                 |
|              |                                |                           |                                     |

### Technical Notes:

Modifications to EDID and input timing support.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.

## Release Notes

**Product Name:** VP-426H2

**Current Version:**

| Ver.Type | Ver No. | Date      |
|----------|---------|-----------|
| Firmware | 1.07    | July 2018 |
| Software | –       | –         |
| Web      | –       | –         |
| Hardware | –       | –         |

**RN Date:** July 2018

**Reference:** 14151

The following changes were made in this version:

### Modifications:

| QC ID | Modification Description   |
|-------|--|
|       | Updated latest 4K EDID   |
|       | Added support for input timing 2048x1080 (24/25/30/50/60)  |
|       | Added default Digital EDID in EDID management  |
|       | Changed the default EDID to 4K@60 stereo audio.  |
|       | When detected EDID is non-standard EDID, the system will send default 1080p (RGB) to the output. |

### Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description |
|-------|--------------------------|
|       | None listed              |

### Known Limitations (including compatibility limitations):

| QC ID | Limitation Description |
|-------|------------------------|
|       | None listed            |

**Preceding Version:** F - 1.05



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VP-426H2

**Current Version:**

| Ver.Type | Ver No. | Date      |
|----------|---------|-----------|
| Firmware | V1.05   | July 2017 |
| Software | –       | –         |
| Web      | –       | –         |
| Hardware | –       | –         |

**RN Date:** July 2017

**Reference:** 12081

### Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| VP-426H2     | Any                            | Yes                       | N/A                                 |
|              |                                |                           |                                     |

### Technical Notes:

- Modifications were made to the OSD text color and available output resolutions.
- An embedded audio bug was fixed.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VP-426H2

**Current Version:**

| Ver.Type | Ver No. | Date      |
|----------|---------|-----------|
| Firmware |         | July 2017 |
| Software | –       | –         |
| Web      | –       | –         |
| Hardware | –       | –         |

**RN Date:** July 2017

**Reference:** 12081

The following changes were made in this version:

### Modifications:

| QC ID | Modification Description                   |
|-------|--|
|       | Changed OSD green text color.              |
|       | Removed 1600x1200 from output resolutions. |

### Bugs Fixed:

| QC ID | Fixed Bug Description   |
|-------|---|
|       | Embedded audio no longer unmuted when you select Bypass mode and press FREEZE |

**Preceding Version:** F - 1.00



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VP-426H2

**Current Version:**

| Ver.Type | Ver No. | Date          |
|----------|---------|---------------|
| Firmware | 1.00    | December 2016 |
| Software | –       | –             |
| Web      | –       | –             |
| Hardware | –       | –             |

**RN Date:** December 2016

**Reference:** 9779

This is a release note for a new product. For a list of new product features see:

[www.kramerav.com/manual/VP-426H2](http://www.kramerav.com/manual/VP-426H2)

The following changes were made in this version:

### Bugs to be Fixed in Future Version:

| QC ID | Description |
|-------|-------------|
|       | None listed |

### Known Limitations (including compatibility limitations):

| QC ID | Description |
|-------|-------------|
|       | None listed |

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)