



Product Name: VP-427
Current Version: F – 1.14
Version Date: June 2016
Reference: 9752

Release Type:

Firmware Software Hardware New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-427	Any	Yes	N/A

Technical Notes:

- Various video output problems were fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-427
Current Version: F – 1.14
Version Date: June 2016
Reference: 9752

The following changes were made in this version:

Fixes:

- Output was flashing with a new MacBook Pro computer as an HDCP source.
- When the output was 1920x1200 the aspect ratio was wrong and 16:9 name was changed to Letterbox.
- Changing HD color space on the output between YUV and RGB gave the wrong color and caused flashes.
- Changing the output resolution from 1080i to 720p produced no embedded audio or image output.

Known Issues:

- There are no known issues.

Preceding Version: F – 1.06



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-427
Preceding Version: F – 1.06
Version Date: March 2015
Reference: 8433

This is a release note for a new product.

Fixes:

- An HDCP snow problem was fixed.

Modifications:

- The brightness range was changed to 0 to 50 with steps of 5.

Known Issues:

- There are no known issues.

Preceding Version: NP – 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-427
Preceding Version: NP – 1.0
Version Date: May 2014
Reference: 4471

This is a release note for a new product.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com