



Product Name: VP-440
Current Version: F – 1.09
Version Date: March 2016
Reference: 10113

Release Type:

Firmware Software Hardware New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-440	Any	Yes	N/A

Technical Notes:

- Protocol 3000 commands were added and changes were made to Web pages.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-440
Current Version: F – 1.09
Version Date: March 2016
Reference: 10113

The following changes were made in this version:

Added Features:

- Add “#STANDBY” command for P3000
- Add “~01@STANDBY P1 - Off(0)/On(1)” when the user presses the power button on the Web page
- Add S/N command for P3000
- Add the “device in sleep mode” message for P3000. Set command when Standby mode is off
- Add Panel lock function in Menu and Web page
- Reply “ ~01@FACTORY OK “ when the user presses the factory button on the Web page

Fixes:

- “Auto adjust” changed to a button on its Web page
- When switching the inputs and pressing the menu button before the new signal comes up (before switching process is finished), the device hung up and required a power cycle.

Modifications:

- Finetune: “Reset” changed to a button on the Web page
- Improved RS-232 response speed

Known Issues:

- There are no known issues.

Preceding Version: F – 1.08



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: VP-440
Preceding Version: F – 1.08
Version Date: February 2016
Reference: 9939

The following changes were made in this version:

Added Features:

- Add “#STANDBY” command for P3000
- Add S/N command for P3000
- Add the “device in sleep mode“ message for P3000. Set command when Standby mode is off
- Add Panel lock function in Menu and Web page
- Reply “ ~01@FACTORY OK “ when the user presses the factory button on the Web page

Fixes:

- “Auto adjust” changed to a button on its Web page
- “Reset” changed to a button on its Web page

Modifications:

- Finetune: “Reset” changed to a button on the Web page
- Improved RS-232 response speed

Known Issues:

- There are no known issues.

Preceding Version: F – 1.07



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-440
Preceding Version: F – 1.07
Version Date: November 2015
Reference: 9570

The following changes were made in this version:

Added Features:

- Audio DSP features were added to increase MIC functionality
- Added TIMING SHIFT control to Web pages

Fixes:

- Fixed bug with MacBook exiting sleep mode

Known Issues:

- There are no known issues.

Preceding Version: NP – 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-440
Preceding Version: NP – 1.0
Version Date: October 2015
Reference: 7631

This is a release note for a new product.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com