

Release Note

Product Name: VP-461

Current Version:

Ver.Type	Ver No.	Date
Firmware	15-36-12.28425.- 461.P - Beta	January 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: July 2017

Reference: Beta

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-461	Any	Yes	N/A

Technical Notes:

- This is a beta release of the firmware.
- Fixed Mac Book Pro issue.

Codedependency with Other Products and Software:

- There is no codedependency with other products or software.

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
8250	Fixed Mac Book Pro issue

Preceding Version: F – 12.35.20.24832.-461.P



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Note History

Product Name: VP-461
Current Version: F – 12.35.20.24832.-461.P
Version Date: January 2016
Reference: 9492

Release Type:

Firmware Software Hardware New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-461	Any	Yes	N/A

Technical Notes:

- Extensive added features and bug fixes.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Product Name: VP-461
Current Version: F – 12.35.20.24832.-461.P
Version Date: January 2016
Reference: 9492

The following changes were made in this version:

Added Features:

- “No Signal” feature added
- “Auto Switching” feature added
- Input EDID – “Single/Multiple modeline” feature added
- “Image Shift Mode” feature added
- Audio reset P3K command added – “AUD-RESET”

Fixes:



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Release Note History

- VP-461 stopped scanning on DP (Auto Switching)
 - Audio noise from PC input
 - Unit didn't load its default native resolution after factory resetting, but only after switching to PC input
 - No audio out when SDI input was at HD or 3G format
 - No video out after sending "FACTORY" command by serial channel
 - Output resolutions not compatible to standard
 - SDI out – no audio after power off and on
 - Color problem in PIP window when using PC as input by serial channel
 - Input EDID – "Single/Multiple mode line" feature: DP input always set to multiple mode
 - "Analog Take Over" feature is not relevant to PC input – add remark to OSD
-
- Audio pops on analog audio out
 - Picture was shifted and distorted after changing input resolution
 - Analog audio out was interrupted in case of plug in / plug out analog audio in – in spite of "Analog Take over" feature is in OFF state.
 - Significant anti-audio loss measures were added to prevent audio loss problems.
 - Video – When switching between HDCP and non HDCP sources sometimes there was HDCP snow or no output signal.
 - Video – There was image tearing for output resolutions 1080p23.97/24/25/29.97/30.

Known Issues:

- There are no known issues.

Preceding Version: F – 12.26.17.12215.-461.P

Product Name: VP-461

Preceding Version: F – 12.26.17.12215.-461.P

Version Date: September 2015



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Release Note History

Reference: 9999

The following changes were made in this version:

Fixes:

- Y command – Get PiP key function added
- Get “win – cust” command added
- OSD Menu control status - changing input resolution in PiP window mode, changed to "Entire System Control".
- HDMI EDID select– "Hot Plug" operation added

Preceding Version: NP – 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Release Note History

Product Name: VP-461
Preceding Version: NP – 1.0
Version Date: May 2014
Reference: 4445

This is a release note for a new product.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com