



Product Name: VP-792

Current Version:	Ver.Type	Ver No.	Date
	Firmware	294C-10548	January 2017
	Software	–	–
	Web	–	–
	Hardware	–	–

RN Date: January 2017

Reference: 12009

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-792	Any	Yes	N/A

Technical Notes:

- Valid MAC address range was increased.
- There is no change in functionality of the device.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-792

Current Version:

Ver.Type	Ver No.	Date
Firmware	294C-10548	January 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 2017

Reference: 12009

The following changes were made in this version:

Modifications:

QC ID	Description
	Valid MAC address range was increased

Bugs to be Fixed in Future Version:

QC ID	Description
	None listed

Known Limitations (including compatibility limitations):

QC ID	Description
	None listed

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com