

VP-81SIDN		
F – 4.57.15806		
October 2014		
7605		
☐ Software	Hardware	
	F – 4.57.15806 October 2014 7605	F – 4.57.15806 October 2014 7605

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-81SIDN	Any	Yes	N/A

Technical Notes:

• RS-232 communication between VP-81SIDN and SID-X1N was improved.

Codependency with Other Products and Software:

• There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerel.com</u>
Web: <u>www.kramerelectronics.com</u>



Product Name: VP-81SIDN

Current Version: F - 4.57.15806Version Date: October 2014

Reference: 7605

The following changes were made in this version:

Fixes:

• RS-232 communication between VP-81SIDN and SID-X1N was improved.

Known Issues:

• At resolution of 1600x1200, the maximum range is 40m.

Preceding Version: NP - 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com
Web: www.kramerelectronics.com



Product Name: VP-81SIDN **Preceding Version**: NP – 1.0

Version Date: July 2014 (ver.2)

Reference: 3954

This is a release note for a new product.

Known Issues:

• At resolution of 1600x1200, the maximum range is 40m.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com
Web: www.kramerelectronics.com