



**Current Firmware Version:** 3427

**Version Date:** December 2010

**Reference:** 6509

**Kramer Products Affected:**

Product Name	Minimum FW version for upgrade	Recommended for all units	Only if added features are required
VP-8x8AK	Any	Yes	–

**Technical Notes:**

- This version includes various added and removed features.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Current Firmware Version:** 3427  
**Version Date:** December 2010  
**Reference:** 6509

The following changes were made in this version:

**Added Features:**

- Added embedded web page.
- Added signal validity commands.
- Added mute/unmute command.
- Added protocol identification display.

**Modifications:**

- Removed start LF in Protocol 3000.

**Known Issues:**

- There are no known issues.

**Preceding Firmware Version:** None

