

Release Notes

Product Name: VS-211UHD

Current Version:

Type	Number	Date
Firmware	1.2_0000	September 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: September 2018

Reference: 14519

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-211UHD	Any	Yes	Yes

Technical Notes:

- Addressed issue with RC-IR3 control.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: VS-211UHD

Current Version:

Type	Number	Date
Firmware	1.2_0000	September 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: September 2018

Reference: 14519

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
7384	The device connects to KUpload via USB port to upgrade
14387	Addressed issue with RC-IR3 control.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
8129	In a certain setup, the last connected mode doesn't work properly.
11068	In a specific setup, the audio embedded in the HDMI out is quite noisy
11151	Can't copy any EDID to an input using the EDID designer

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
7385	The device works on 5V input
7435	Second press on OFF button on remote control returns the output to the input that was selected before the presses
7477	In a certain situation Last connected occasionally doesn't work
7479	There is analog signal on output during the switching from HDCP on to off

Preceding Version: 1.1



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: VS-211UHD

Current Version:

Type	Number	Date
Firmware	1.1	May 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: May 2017

Reference: 11669

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-211UHD	Any	Yes	N/A

Technical Notes:

- Default EDID was changed and product supported by EDID Designer.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: VS-211UHD

Current Version:

Type	Number	Date
Firmware	1.1	May 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: May 2017

Reference: 11669

The following changes were made in this version:

New Features:

	New Feature Description
	Support for EDID Designer

Modifications:

QC ID	Modification Description
	Default EDID was updated
7993	An analog input signal was output during the switching from input with analog audio to input with embedded audio

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
8129	In a certain setup, the last connected mode doesn't work properly.
11068	In a specific setup, the audio embedded in the HDMI out is quite noisy

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
7385	The device works on 5V input
7435	Second press on OFF button on remote control returns the output to the input that was selected before the presses
7477	In a certain situation Last connected occasionally doesn't work
7479	There is analog signal on output during the switching from HDCP on to off

Preceding Version: F – 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: VS-211UHD

Current Version:

Type	Number	Date
Firmware	1.0	February 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: February 2017

Reference: 9367

This is a release note for a new product. For a list of new product features see:
www.kramerav.com/manual/VS-211UHD

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
7993	There is analog input signal on output during the switching from input with analog audio to input with embedded audio
8129	Last Connected problem with SID-X1N and PT-572+

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	No support for EDID Designer
7385	There is wrong input power
7435	Second press on OFF button on remote control returns the output to the input that was selected before the presses
7477	Last connected sometimes doesn't work
7479	There is analog signal on output during the switching from HDCP on to off

Preceding Version: F – N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com