

## Release Note

**Product Name:** VS-8FDxl

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	1.1.24	July 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 2017

**Reference:** 10807

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-8FDxl	N/A	N/A	N/A

**Technical Notes:**

- This is a release note for a new product.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note History

**Product Name:** VS-8FDxI

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	1.1.24	July 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 2017

**Reference:** 10807

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/VS-8FDxI>

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
10399	When the UDP port is changed from the default 50000, the Kramer Network cannot automatically discover the device

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)