



**Product Name:** VSM-4x4HFS  
**Current Version:** F – 2.0  
**Version Date:** March 2015  
**Reference:** 8547

**Release Type:**

Firmware       Software       Hardware       New Product

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VSM-4x4HFS	Any	Yes	N/A

**Technical Notes:**

- An option to load firmware via Ethernet was replaced by a USB option and control options were fixed.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VSM-4x4HFS  
**Current Version:** F – 2.0  
**Version Date:** March 2015  
**Reference:** 8547

The following changes were made in this version:

**Added Features:**

- An option to load firmware via Ethernet was replaced by a USB option. This frees memory space for future upgrades.
- Ethernet UDP Control was enabled.
- Missing commands and RS-232 echoing for all P3K commands was added.
- Support was added for input/output label changes that display on the screen, with a smaller font that supports 12 characters.

**Known Issues:**

- There are no known issues.

**Preceding Version:** F – 1.15



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)