



Product Name: WP-580T, WP-580R

Current Version: F – 2.31.00 (Valens)

Version Date: December 2015

Reference: 9197

Release Type:

Firmware Software Hardware New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
WP-580T	Any	Yes	N/A
WP-580T/US	Any	Yes	N/A
WP-580T/EU	Any	Yes	N/A
WP-580R	Any	Yes	N/A
WP-580R/US	Any	Yes	N/A
WP-580R/EU	Any	Yes	N/A

Technical Notes:

- A missing video problem was fixed.
- This upgrade can be done only in the Kramer office. Please contact your Kramer dealer for details.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: WP-580T, WP-580R
Current Version: F – 2.31.00 (Valens)
Version Date: December 2015
Reference: 9197

The following changes were made in this version:

Fixes:

- On some screens, video is missing with certain resolutions (for example, XGA on some Dell monitors).

Known Issues:

- There are no known issues.

Preceding Version: F – 2.30.90 (Valens)



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: WP-580T, WP-580R
Current Version: F – 2.30.90 (Valens)
Version Date: July 2014
Reference: 7604

Fixes:

- When the transmitter and receiver were powered up together, the monitor did not always receive video.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com