# KRAMER ELECTRONICS RELEASE NOTE



Product Name:	WP-580TXR, W	'P-580RXR	
<b>Current Version:</b>	F – 1.31.00 (Valens)		
Version Date:	December 2015		
Reference:	9219		
<b>Release Type:</b>	Software	Hardware	New Product

# **Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
WP-580Txr	Any	Yes	N/A
WP-580Txr/US	Any	Yes	N/A
WP-580Txr/EU	Any	Yes	N/A
WP-580Rxr	Any	Yes	N/A
WP-580Rxr/US	Any	Yes	N/A
WP-580Rxr/EU	Any	Yes	N/A

# **Technical Notes:**

- A missing video problem was fixed.
- This upgrade can be done only in the Kramer office. Please contact your Kramer dealer for details.

## **Codependency with Other Products and Software:**

• There is no codependency with other products or software.



# **KRAMER ELECTRONICS RELEASE HISTORY**



Product Name:	WP-580TXR, WP-580RXR
<b>Current Version:</b>	F – 1.31.00 (Valens)
Version Date:	December 2015
Reference:	9219

The following changes were made in this version:

#### Fixes:

• On some screens, video is missing with certain resolutions (for example, XGA on some Dell monitors).

## **Known Issues:**

• There are no known issues.

Preceding Version: F – 1.30.90 (Valens)



KRAMER ELECTRONICS, Ltd. E-mail: <u>info@kramerel.com</u>

Web: <u>www.kramerelectronics.com</u>



Product Name:	WP-580TXR, WP-580RXR
<b>Current Version:</b>	F – 1.30.90 (Valens)
Version Date:	July 2014
Reference:	7507

#### Fixes:

• When the transmitter and receiver were powered up together, the monitor did not always receive video.

## **Known Issues:**

• There are no known issues.

Preceding Version: NP - 1.0





Product Name:	TP-580TXR, TP-580RXR
Current Version:	NP – 1.0
Version Date:	April 2013
Reference:	2499

This is a release note for a new product.

• Kramer strongly recommends using shielded cable with this product.

### **Known Issues:**

• There are no known issues.

Preceding Version: N/A

