



Software Name: EDID Designer
Current Software Version: 1.0.0.53
Version Date: April 2012
Reference: 2236

Technical Notes:

Various functional errors were fixed.

Kramer Products Affected:

Product Name	Required Firmware Version
VA-2H	1.1
VS-81KSi	3607
WP-501	3.3.1.3782



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Software Name: EDID Designer
Current Software Version: 1.0.0.53
Version Date: April 2012
Reference: 2236

The following changes were made in this version:

Fixes:

- A failure to save the EDID from download or pressing the save button was fixed.
- An Open Monitor EDID error in Windows 7 was fixed.
- A program crash when trying to read an EDID from a non-existing port was fixed.

Known Issues:

- There are no known issues.

Preceding Software Version: 1.0.0.43



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Software Name: EDID Designer
Preceding Software Version: 1.0.0.43
Version Date: September 2011

The following changes were made in this version:

Added Features:

- Support for the VA-2H was added.

Fixes:

- The status row now displays the current status.
- The "Command" menu is disabled when the status is "Disconnected".
- When illegal data is entered in numeric fields an error message is displayed.
- "Save EDID", "Save EDID as" and "Download to" were fixed to work properly.

Known Issues:

- There are no known issues.

Preceding Software Version: 1.0.0.32



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com