



Product Name: K-Router Plus

Current Version: S – 2.0.30

Version Date: June 2014

Reference: 7255

Release Type:

☐ Firmware ☒ Software ☐ Hardware ☐ New Product

Technical Notes:

- This version fixes several bugs.

Codependency with Other Products and Software:

Product Name	Comments
VP-16x18AK	
VS-1616D, VS-3232D	Works only via RS-232
VS-42HDCP, VS-44HDCP	
VS-42HN, VS-44HN	
VS-62H	
VS-88FO, VS-44FO	
VS-88HDxI	
VS-88HFS	
VS-88HN, VS-48HN, VS-84HN, VS-66HN	



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com



Product Name: K-Router Plus
Current Version: S – 2.0.30
Version Date: June 2014
Reference: 7255

Fixes:

- The machine configuration is correctly restored on the application GUI.
- Firmware update is not available for the VS-88HFS.
- K-Router Plus now reads the EDID file correctly from all devices, in both TCP and serial modes.

Known Issues:

- K-Router Plus only works with Protocol 3000. IR control does not work on the codependent products when the product is set to Protocol 3000 or controlled by K-Router Plus. To control the product using IR, the product must set to Protocol 2000 and use the previous version of K-Router.
- On the VS-1616D and the VS-3232D K-Router Plus works only via RS-232.

Preceding Version: S – 2.0.28.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: K-Router Plus
Preceding Version: S – 2.0.28.0
Version Date: February 2014
Reference: RD-001026

Known Issues:

- K-Router+ only works with Protocol 3000. IR control does not work on the codependent products when the product is set to Protocol 3000 or controlled by K-Router+. To control the product using IR, the product must set to Protocol 2000 and use the previous version of K-Router.

Preceding Version: S – N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com