



**Current Firmware Version:** 0.9.0.5512  
**Version Date:** December 2011  
**Reference:** 1556

**Kramer Products Affected:**

Product Name	Minimum FW version for upgrade	Recommended for all units	Only if added features are required
PIP-4	Any	Yes	–

**Technical Notes:**

- This version is the initial release for production.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramerelectronics.com](mailto:info@kramerelectronics.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Current Firmware Version:** 0.9.0.5512  
**Version Date:** December 2011  
**Reference:** 1556

The following changes were made in this version:

**Added Features:**

- Initial production release.

**Known Issues:**

- After upgrading the firmware, a regular reset does not change the firmware version. A manual power reset must be performed.
- Inconsistent mouse jumps happen intermittently. To fix, perform a power reset.

**Preceding Firmware Version:** N/A

