



Product Name: RB-6

Current Version:

Ver.Type	Ver No.	Date
Firmware	v02.00.00.32264	January 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 2017

Reference: 11653

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RB-6	Any	Yes	N/A

Technical Notes:

- An Ethernet communication problem was fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: RB-6

Current Version:

Ver.Type	Ver No.	Date
Firmware	v02.00.00.32264	January 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 2017

Reference: 11653

The following changes were made in this version:

Bugs Fixed:

QC ID	Description
9659	After changing the TCP Port it is not possible to communicate with the device either in TCP or UDP

Bugs to be Fixed in Future Version:

QC ID	Description
1414	When using Internet Explorer browser for 32-bits, the Scheduler doesn't work

Known Limitations (including compatibility limitations):

QC ID	Description
	None listed

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com