



Product Name: RC-78R

Current Version:

Ver.Type	Ver No.	Date
Firmware	4.0.34.30581	October 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: October 2016

Reference: 11182

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-78R	Any	Yes	N/A

Technical Notes:

- A Web page issue was fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramere.com

Web: www.kramerelectronics.com



Product Name: RC-78R

Current Version:	Ver.Type	Ver No.	Date
	Firmware	4.0.34.30581	October 2016
	Software	–	–
	Web	–	–
	Hardware	–	–

RN Date: October 2016

Reference: 11182

The following changes were made in this version:

Bugs Fixed:

QC ID	Description
5596	With security switched ON the Web page sometimes did not load

Bugs to be Fixed in Future Version:

QC ID	Description
4915	KNET delays of 2-3 seconds up to 10 seconds when connecting up to 4 x RC-78R
7594	Device startup CMD (when using K-Config2) for RC-78R connected to VP-311 does not work when using P2K (button action works OK)

Preceding Version: F - 4.0.33.29083



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramere.com

Web: www.kramerelectronics.com



Product Name: RC-78R

Preceding Version:

Ver.Type	Ver No.	Date
Firmware	4.0.33.29083	August 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: August 2016

Reference: 11009

The following changes were made in this version:

New Features:

	Description
	Support for new flash component
	Improved PJLINK protocol handling

Bugs to be Fixed in Future Version:

QC ID	Description
4915	KNET delays of 2-3 seconds up to 10 seconds when connecting up to 4 x RC-78R
7594	Device startup CMD (when using K-Config2) for RC-78R connected to VP-311 does not work when using P2K (button action works OK)

Preceding Version: F – 4.0.29.24637



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramere.com

Web: www.kramerelectronics.com

KRAMER ELECTRONICS RELEASE NOTE



Product Name: RC-78R
Preceding Version: F – 4.0.29.24637
Version Date: February 2016
Reference: 10062

Release Type:

Firmware Software Hardware New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-78R	Any	Yes	N/A

Technical Notes:

- Support for K-Config 3 features. The features are described in the updated K-Config guide available from our Website.

Codependency with Other Products and Software:

Product Name	Comments
K-Config 3	Ver 3.1.1.3

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: RC-78R
Current Version: F – 4.0.29.24637
Version Date: February 2016
Reference: 10062

The following changes were made in this version:

Modifications:

- Support for K-Config 3 features.

Known Issues:

QC ID	Description
4915	KNET delays of 2-3 seconds up to 10 seconds when connecting up to 4 x RC-78R
5206	Request to add an option for Power Cycle / Device Reset when using TCP/IP Protocol

Preceding Version: F – 4.0.15.11355



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: RC-78R
Current Version: F – 4.0.15.11355
Version Date: January 2014
Reference: 6378

The following changes were made in this version:

Added Features:

Added support for K-Config 2 new relevant features:

- K-Config 2 – Support for new query mechanism
- K-Config 2 – Supports new tables
- K-Config 2 – Supports new DELAY
- K-Config 2 – Supports "Test command"
- K-Config 2 – Supports 10 Ethernet clients

Fixes:

- Various bugs were fixed and performance stabilized.

Modifications:

- Speed enhancements were made.

Known Issues:

- There are no known issues.

Preceding Version: F - 3.5.2.8161



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com