

Release Note

Product Name: Site-CTRL

Current Version:	Ver.Type	Ver No.	Date
	Firmware		
	Software	2.0.31	August 2017
	Web	–	–
	Hardware	–	–

RN Date: December 2017

Reference: 13031

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
Site-CTRL	Any	Yes	N/A

Technical Notes:

- Fixed bugs.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Note History

Product Name: Site-CTRL

Current Version:

Ver.Type	Ver No.	Date
Firmware	-	
Software	2.0.31	August 2017
Web	-	-
Hardware	-	-

RN Date: December 2017

Reference: 13031

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
11381	Issues with updating time, FW and configuration and with "Main display status" and "Lamp hour usage" columns.
11562	'Device list' on the 3 update windows has code syntax instead of IP addresses of the devices.

Preceding Version: S – 2.0.0.27



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Note History

Product Name: Site-CTRL

Current Version:

Ver.Type	Ver No.	Date
Firmware	–	–
Software	2.0.0.27	July 2016
Web	–	–
Hardware	–	–

RN Date: August 2016 (Ver. 2)

Reference: 10987

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
Site-CTRL	Any	Yes	N/A

Technical Notes:

- Various bugs were fixed.

Codedependency with Other Products and Software:

Product Name	Comments
RC-XX	All RC-XX devices
SL-1XX	All SL-1XX devices

Product Name: Site-CTRL

Current Version:

Ver.Type	Ver No.	Date
Firmware	–	–
Software	2.0.0.27	July 2016
Web	–	–
Hardware	–	–

RN Date: August 2016 (Ver. 2)

Reference: 10987



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Note History

The following changes were made in this version:

Bugs Fixed:

QC ID	Description
8048	Editing the IP of a device, to an existing IP merges both devices on the 'Room List' tab
8081	Pressing the "msg" button causes the app to close
8104	Editing a room caused an exception
8235	Having 2 or more projectors with lamp hour queries is not distinguishable on the event log of the Site-Ctrl app
8287	Adding a time schedule, when its end date is the same as the start date, causes an exception
8292	Performance: The app hangs when dealing with more than 20 RCs on the 'Room List'
8295	Increased 'ERROR -> COMMUNICATION -> Room_Status' timeout when RC does not respond
8321	Exception when logging into Site-Ctrl, when no light SQL was found
8382	On some machines: SQLite is not loaded properly and causes a "Wrong login credentials" message upon correct login (even when logged in as a user)



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Note History

Bugs to be Fixed in Future Version:

QC ID	Description
2410	'Room name start index' needs limitation (Field validation issue)
2413	Clicking 'Cancel' in the warning message: "Do you want to save changes....?" after editing the 'Email notification' area, saves the changes instead of ignoring them (also, the message appears after switching to another tab instead of before the switch)
2438	The device's password cannot be changed
2450	Resizing the window is only possible on the right-hand side
2453 & 8384	Localization issues
2483	Defining more than one email in the 'Settings' tab sends the email to the last address on the list
2496	Allow sending mails when the security is on
2510 & 2615	Minimizing causes Site-CTRL's task bar icon to disappear
2512	Two simultaneous update processes cause an exception in an upload event
2508, 2513, 2515, 2601, 2627	Scheduling window issues
6333	The dragging feature in the Location/Sites/Rooms tree does not work properly
8102	Opening the project after renaming the location name keeps the old name
8299	Filtering the 'Event log' by RCs IP addresses behaves incorrectly
8370	Wrong calculation of lamphour usage percentage on some of the RCs in the room list
8385	Happened once: An unhandled exception occurred after the main screen was displayed, immediately after the login

Preceding Version: N S – 2.0.0.x



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Note History

Product Name: Site-CTRL
Current Version: S – 2.0.0.x
Version Date: April 2014
Reference: Beta Version

Release Type:

Firmware Software Hardware New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
Site-CTRL	NR	NR	Yes

Technical Notes:

- This is a Beta version release. There are still open issues, mainly with the messaging and emailing system which will be fixed for the first released version.
- Due to major changes in the query system, messages sent to Site-CTRL by queries configured in versions earlier than K-Config 2.0.0.X are not supported in this version.
- The format of messages sent from the master room controller to the Site-CTRL site-monitoring application was updated.
- For the Site-Ctrl solution to operate correctly, **all three** software components (device firmware, K-Config and Site-CTRL) **must** be of the same release version. We strongly advise taking this into consideration before upgrading the firmware on devices already installed or before updating the Site-CTRL installation to the latest version of Site-CTRL 2. If your present AV site is running Site-CTRL configured with the older version of K-Config, consult Kramer Tech support on whether to upgrade the firmware used on this installed AV site.

Codependency with Other Products and Software:



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Note History

Product Name	Required Firmware Version
SV-551	This version is not compatible with the SV-551. Users of the SV-551 should continue using older Site-CTRL versions
SV-552	Minimum required SV-552 firmware version for maximum compatibility - 4.0.15.11355
WP-500	This version is not compatible with the WP-500. Users of the WP-500 should continue using older Site-CTRL versions
WP-501	This version is not compatible with the SV-551. Users of the WP-501 should continue using older Site-CTRL versions
SL-1	Minimum required firmware version for maximum compatibility – 4.0.15.11355. In some cases, we recommend not upgrading the firmware and should continue using older Site-CTRL versions. See details in the SL-1 Release notes
SL-12	Minimum required firmware version for maximum compatibility - 4.0.15.11355
SL-14RC	Minimum required firmware version for maximum compatibility will be available in a few weeks. In some cases, we recommend not upgrading the firmware and should continue using older Site-CTRL versions. See details in the SL-14RC Release notes
RC-63D series	Minimum required RC-6X firmware version for maximum compatibility - 4.0.15.11355
RC-63A series	Minimum required RC-6X firmware version for maximum compatibility - 4.0.15.11355
RC-62 series	Minimum required RC-6X firmware version for maximum compatibility - 4.0.15.11355
RC-53D series	Minimum required firmware version for maximum compatibility - 3.2.2.3166



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Note History

Product Name	Required Firmware Version
RC-53DLC series	Minimum required firmware version for maximum compatibility - 3.2.2.3480
RC-74DL series	Minimum required firmware version for maximum compatibility - 4.0.15.11355
RC-2	Minimum required firmware version for maximum compatibility – 11696
RC-2C	Minimum required firmware version for maximum compatibility - 5866
RC-52/N	Minimum required firmware version for maximum compatibility – 5866
RC-63DLN series	Minimum required firmware version for maximum compatibility – 4.0.15.11355
RC-712M / RC-76M	Minimum required firmware version for maximum compatibility – 4.0.15.11355
RC-78R / RC-76R	Minimum required firmware version for maximum compatibility – 4.0.15.11355
RC-13TC	Minimum required firmware version for maximum compatibility will be available in a few weeks



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Note History

Product Name: Site-CTRL
Current Version: S – 2.0.0.x
Version Date: April 2014
Reference: Beta Version

This version includes the following changes from versions 1.x.x.x:

Added Features:

- AV site can be divided into a tree view
- The user can select rooms to view in the main room view page
- Scheduled task support (FW upgrade, CFG uploads, Internal clock syncing)
- Support for K-Config 2.0.0.X queries and messaging system

Modifications:

- Improved stability when a large number of rooms are monitored

Known Issues:

- To be announced with the first released version.

Preceding Version: S - 1.x.x.x



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com