

Release Note

Product Name: VP-426H2

Current Version:

Ver.Type	Ver No.	Date
Firmware	V1.05	July 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: July 2017

Reference: 12081

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-426H2	Any	Yes	N/A

Technical Notes:

- Modifications were made to the OSD text color and available output resolutions.
- An embedded audio bug was fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Release Note

Product Name: VP-426H2

Current Version:

Ver.Type	Ver No.	Date
Firmware		July 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: July 2017

Reference: 12081

The following changes were made in this version:

Modifications:

QC ID	Modification Description
	Changed OSD green text color.
	Removed 1600x1200 from output resolutions.

Bugs Fixed:

QC ID	Fixed Bug Description
	Embedded audio no longer unmuted when you select Bypass mode and press FREEZE

Preceding Version: F - 1.00

Release Note History

Product Name: VP-426H2

Current Version:

Ver.Type	Ver No.	Date
Firmware	1.00	December 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 2016

Reference: 9779

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/VP-426H2>

The following changes were made in this version:

Bugs to be Fixed in Future Version:

QC ID	Description
	None listed

Known Limitations (including compatibility limitations):

QC ID	Description
	None listed

Preceding Version: N/A