



Product Name: VP-553, VP-553xl

Current Version: F – 1.41

Version Date: February 2016

Reference: 10083

Release Type:

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-553	Any	Yes	N/A

Technical Notes:

- Various Web, audio, P3K and other issues were fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-553, VP-553xl

Current Version: F – 1.41

Version Date: February 2016

Reference: 10083

The following changes were made in this version:

Fixes:

- Scrollbars: Auxiliary Level and Output Volume were out of limits
- The OSD menu and WEB scaling were not same when the PC input was chosen
- Comma in beginning of string when you choose to write EDID to an input that is not HDMI1

Known Issues:

- There are no known issues.

Preceding Version: F – 1.40



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: VP-553
Preceding Version: F – 1.40
Version Date: January 2016
Reference: 9444

The following changes were made in this version:

Added Features:

- Balanced audio output follows Output 1 or 2.
- Protocol 3000 volume and power commands added.
- Front panel echoing added.
- Mic gain added to Web page.
- Added “ AUDIO OUT” in SID-X2N on Web page
- When pressing the Step in button on SID-X2N, audio follows video.
- Added STANDBY ON/OFF command.
- Added UDP echoing.

Fixes:

- Web bugs were fixed.
- P3K bugs were fixed.
- A TP to PC switching bug was fixed.
- Intermittent audio bugs were fixed.
- Fail color space after change output resolution.
- The protocol command on the serial terminal window now echoes while pressing on unit button.
- Equalizer parameters after factory reset were fixed.

Modifications:



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



- EDID mechanism changed to be compatible with PT-571.
- The SID-X2N Step-in button lights when switching to its connected HDBT input, by pressing the VP-553 front panel buttons.
- Changing the output resolution via OSD or remote control when the input resolution is WUXGA, hung the device.
- Disable the 'Logout after x minutes...' checkbox when the 'Authenticate Web page access' checkbox is unchecked.
- Add the 'Microphone Gain' feature to the Web page, once the 'Line/Mic' DIP-switch is set to 'Mic'.

Known Issues:

- There are no known issues.

Preceding Version: F – 0.30



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-553
Preceding Version: F – 0.30
Version Date: October 2014
Reference: 7887

Release Type:

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-553	No	Yes	N/A

Technical Notes:

- Data routing was added.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-553
Current Version: F – 3.0
Version Date: October 2014
Reference: 7887

Added Features:

- Data Routing was added.

Fixes:

- Bugs were fixed.

Known Issues:

- There are no known issues.

Preceding Version: NP – 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-553
Preceding Version: NP – 1.0
Version Date: June 2014
Reference: 4704

This is a release note for a new product.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com