



**Product Name:** VP-553  
**Current Version:** F – 3.0  
**Version Date:** October 2014  
**Reference:** 7887

**Release Type:**

Firmware       Software       Hardware       New Product

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-553	No	Yes	N/A

**Technical Notes:**

- Data routing was added.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VP-553  
**Current Version:** F – 3.0  
**Version Date:** October 2014  
**Reference:** 7887

**Added Features:**

- Data Routing was added.

**Fixes:**

- Bugs were fixed.

**Known Issues:**

- There are no known issues.

**Preceding Version:** NP – 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VP-553  
**Preceding Version:** NP – 1.0  
**Version Date:** June 2014  
**Reference:** 4704

This is a release note for a new product.

**Known Issues:**

- There are no known issues.

**Preceding Version:** N/A



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)