



Product Name: VP-770
Current Version: F – ARM9 -11368; ARM7 - 10986
Version Date: December 2013
Reference: 6395

Release Type:

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-770	Any	Yes	N/A

Technical Notes:

- Various features were added and various problems were fixed.
- After the upgrade, the following firmware version displays in the info screen: 03.26.46.11368.10986.P.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: VP-770
Current Version: F – ARM9 -11368/ARM7 - 10986
Version Date: December 2013
Reference: 6395

The following changes were made in this version:

New Features

For a detailed description of the new features, see the updated User Manual on our website.

- A built-in remote control emulation Web page was added.
- Support was added for the different control commands.
- A port tunneling feature that allows communicating commands via ETH and DGKAT ports was added.
- Settings of the customized window are now permanently saved.
- Incremental increase/decrease support was added to control protocol commands.
- Emergency Alert System was implemented.
- Convenient toggling was added between Main and PIP windows controls while browsing in the OSD MENU.
- The ability was added to select the color depth parameter in the input's EDID.
- IP address, input, and master connection were added to the Info screen.
- In the OSD, under Scale->Output->HDCP Mode, "Follow input" and "Follow output" options were added.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Fixes:

- Fast and smooth PiP insertion no longer affects the main window video and audio streaming.
- When the PIP window HW parameter was set higher than 1280, the picture was distorted.
- HDMI plugin detection was improved.
- In the EDID, mistakes in the details of some resolutions were fixed.
- Multiple minor bugs were fixed.

Known Issues:

- Auto positioning in DisplayPort can create green bars.

Preceding Version: F – 9117



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: VP-770
Preceding Version: F – 9117
Version Date: July 2013
Reference: 5645

The following changes were made in this version:

Fixes:

- Many bugs in the previous version were fixed and new features were added. Refer to the updated User Manual on the Kramer Website.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com