



Product Name: VP-440

Current Version:

Ver.Type	Ver No.	Date
Firmware	1.13	July 2016
Software	–	–
Web	–	–
Hardware	–	–

Rel Note Date: July 2016

Reference: 10889

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-440	Any	Yes	N/A

Technical Notes:

- Various bugs were fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-440

Current Version:

Ver.Type	Ver No.	Date
Firmware	1.13	July 2016
Software	–	–
Web	–	–
Hardware	–	–

Rel Note Date: July 2016

Reference: 10889

The following changes were made in this version:

New Features:

	Description
	There is no change in functionality.

Bugs Fixed:

QC ID	Description
7174	The IP, DHCP and control port did not reset to their default values after a factory reset
7219	Redesigned the graphics of some Web pages
8123	STANDBY command worked incorrectly
8155	If state is not changed, the response should be "OK"
8565	Fixed intermittent HDBT dropout when connected to a Panasonic projector
Case 143925	Corrected color issues
Case 142387	Added Volume bar display
	Fixed EDID-DIGITAL one byte error seen on Quantum Data Analyzer



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Bugs to be Fixed in Future Version:

QC ID	Description
5091	Implement more DSP audio functions
6827	Quantum Data Analyzer gives a negative reading for VSYNC at 1680x1050 resolution
7289	Missing DRC option in the Web page (seen only in the OSD)
7290	Missing spaces before and after the ampersand in Lock menu entries (in both OSD and Web page)
7605-7608	Unable to know the HDCP input/output status by P3K commands and Web GUI
7671	With TIMING SHIFT set to ON, 1400x1050 is not detected by Quantum Data Analyzer
8570	Spacing between parameters in the Advanced Web page is inconsistent
8571	Missing explanations for some parameters in the Advanced page
8572	"Input name" field is not reset to default after running a Soft factory reset

Known Limitations (including compatibility limitations):

QC ID	Description
5189	VP-440 recognizes 1680x1050 resolution as 1400x1050
5747	HDMI output monitor is affected from another monitor connected to HDBT output but switched to a different input

Preceding Version: F – 1.10



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-440
Preceding Version: F – 1.10
Version Date: May 2016
Reference: 10472

Release Type:

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-440	Any	Yes	N/A

Technical Notes:

- Overview of changes.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: VP-440
Current Version: F – 1.10
Version Date: May 2016
Reference: 10472

The following changes were made in this version:

Added Features:

- Two web page options (advanced page) were added:
 - Mutes when video freeze ON/OFF.
 - Mutes when video blank ON/OFF.
- Allows the use of the mic even when no video is present.
- Support for four Ethernet clients was added.
- The P3K RESET command & soft factory reset were added to the Web.

Fixes:

- FCT-SN command was not invisible in help list.
- The copyright year and Kramer telephone number were corrected.

Modifications:

- "Name" was changed to "Serial Number" in the web page

Known Issues:

- There are no known issues.

Preceding Version: F – 1.09



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-440
Preceding Version: F – 1.09
Version Date: March 2016
Reference: 10113

The following changes were made in this version:

Added Features:

- Add “#STANDBY” command for P3000
- Add “~01@STANDBY P1 - Off(0)/On(1)” when the user presses the power button on the Web page
- Add S/N command for P3000
- Add the “device in sleep mode” message for P3000. Set command when Standby mode is off
- Add Panel lock function in Menu and Web page
- Reply “ ~01@FACTORY OK “ when the user presses the factory button on the Web page

Fixes:

- “Auto adjust” changed to a button on its Web page
- When switching the inputs and pressing the menu button before the new signal comes up (before switching process is finished), the device hung up and required a power cycle.

Modifications:

- Finetune: “Reset” changed to a button on the Web page
- Improved RS-232 response speed

Known Issues:

- There are no known issues.

Preceding Version: F – 1.08



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-440
Preceding Version: F – 1.08
Version Date: February 2016
Reference: 9939

The following changes were made in this version:

Added Features:

- Add “#STANDBY” command for P3000
- Add S/N command for P3000
- Add the “device in sleep mode” message for P3000. Set command when Standby mode is off
- Add Panel lock function in Menu and Web page
- Reply “ ~01@FACTORY OK “ when the user presses the factory button on the Web page

Fixes:

- “Auto adjust” changed to a button on its Web page
- “Reset” changed to a button on its Web page

Modifications:

- Finetune: “Reset” changed to a button on the Web page
- Improved RS-232 response speed

Known Issues:

- There are no known issues.

Preceding Version: F – 1.07



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-440
Preceding Version: F – 1.07
Version Date: November 2015
Reference: 9570

The following changes were made in this version:

Added Features:

- Audio DSP features were added to increase MIC functionality
- Added TIMING SHIFT control to Web pages

Fixes:

- Fixed bug with MacBook exiting sleep mode

Known Issues:

- There are no known issues.

Preceding Version: NP – 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-440
Preceding Version: NP – 1.0
Version Date: October 2015
Reference: 7631

This is a release note for a new product.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com