



**Product Name:** VP-444  
**Current Version:** F – 1.26 (Beta)  
**Version Date:** March 2015  
**Reference:** Beta

**Release Type:**

☐ Firmware ☐ Software ☐ Hardware ☒ New Product

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-444	Any	Yes	N/A

**Technical Notes:**

- This beta version improves audio compatibility when connected to a PT-571.
- Added commands for VOLUME UP and VOLUME DOWN

**Codependency with Other Products and Software:**

Product Name	Comments
PT-571	
PT-572	



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramerelect.com](mailto:info@kramerelect.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VP-444  
**Current Version:** F – 1.26 (Beta)  
**Version Date:** March 2015  
**Reference:** Beta

The following changes were made in this version:

**Added Features:**

- Volume + and – commands were added for input and output. See updated Protocol table on the website

**Fixes:**

- When a PT-571 is connected to the scaler, audio does not pass to the output.

**Preceding Version:** NP – 1.22 (Beta)



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VP-444  
**Preceding Version:** F – 1.22 (beta)  
**Version Date:** February 2015  
**Reference:** 4444

The following changes were made in this version:

**Added Features:**

- Options to blank the video output were added.
- Supports audio even if video is not present.

**Fixes:**

- A bug in the "Last Connected" feature was fixed.
- Now includes front-panel serial port echoing.
- P3K is now supported when connected via UDP.
- Allows use of front panel buttons while the OSD's volume value is displayed.
- Fixes a bug that sometimes affected EDID file copying.
- Minor bugs were fixed.



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



### **Known Issues:**

- The talk-over feature is not yet implemented.
- Performing several actions on the device can cause the Web page to stop controlling the unit.
- There may be a "popping" noise when cycling power.
- The input resolution may display incorrectly after copying the EDID to a MacBook's input
- In a few cases, the first characters of the input name are deleted.

**Preceding Version:** NP - 1.0



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VP-444  
**Preceding Version:** NP – 1.0  
**Version Date:** January 2015 (Ver 2)  
**Reference:** 5473

This is a release note for a new product.

**Known Issues:**

- The talk-over feature is not yet implemented.
- P3K is not yet supported when connected via UDP.
- Performing several actions on the device can cause the Web page to stop controlling the unit.
- There may be a "popping" noise when cycling power.
- The input resolution may display incorrectly after copying the EDID to a MacBook's input
- The "Last Connected" feature has issues if the current input is unplugged.
- No echo is sent on the serial port when controlled via the front panel.
- The front panel's buttons are disabled while the OSD's volume value is displayed.
- There may be differences between the original EDID and copied EDID files.
- In a few cases, the first characters of the input name are deleted.

**Preceding Version:** N/A



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)