



Product Name: VS-44HN
Current Version: F – 2.2
Version Date: March 2013
Reference: 5073

Release Type:

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-44HN	Any	Yes	N/A

Technical Notes:

- A new command was added and a command problem was fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelectronics.com

Web: www.kramerelectronics.com



Product Name: VS-44HN
Current Version: F – 2.2
Version Date: March 2013
Reference: 5073

The following changes were made in this version:

Added Features:

- A Reset command was added for Protocol 2000.

Fixes:

- When storing from the keypad, the device did not send the relevant command to K-Router.

Known Issues:

- There are no known issues.

Preceding Version: F - 1.3



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Preceding Version: F - 1.3
Version Date: August 2012 (Update)
Reference: 3848

The following changes were made in this version:

Fixes:

- The numbering of the setups under front panel buttons was in the wrong order.
- When one of the outputs was set off K-Router reported that all outputs were off.

Known Issues:

- The IR remote control does not work when the device is set to Protocol 3000. It does work when the device is set to Protocol 2000.

Preceding Firmware Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com