



Product Name: VS-88FO
Current Version: F – 2.1.11191
Version Date: December 2013
Reference: 6441

Release Type:

Firmware Software Hardware New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-88FO	Any	Yes	N/A

Technical Notes:

- Commands were fixed and machine number settings were changed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: VS-88FO
Current Version: F – 2.1.11191
Version Date: December 2013
Reference: 6441

The following changes were made in this version:

Fixes:

- The machine number settings by DIP switches were changed to 1...15.
- Protocol commands for Store and Recall were fixed.

Known Issues:

- There are no known issues.

Preceding Version: F – 2.0.8128



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com