



**Product Name:** VS-84HN  
**Current Version:** F – 3.2  
**Version Date:** June 2015  
**Reference:** 8935

**Release Type:**

☒ Firmware      ☐ Software      ☐ Hardware      ☐ New Product

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-84HN	Any	Yes	N/A

**Technical Notes:**

- An audio problem was corrected together with other bugs.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramerel.com](mailto:info@kramerel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VS-84HN  
**Current Version:** F – 3.2  
**Version Date:** June 2015  
**Reference:** 8935

The following changes were made in this version:

**Modifications:**

- All FCT commands were changed to be hidden in the help list.

**Fixes:**

- There was an occasional audio loss when changing parameters of the inputted signal.
- The manufacture name in the default EDID was correct to "KMR".
- Occasionally there was no video when connecting DGKat extenders at the output.

**Known Issues:**

- There are no known issues.

**Preceding Version:** F – 3.1



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VS-84HN  
**Preceding Version:** F – 3.1  
**Version Date:** October 2014  
**Reference:** 7859

The following changes were made in this version:

**Added Features:**

- Fast switching was added.
- An HDCP ON/OFF option was added.

**Fixes:**

- Various bugs were fixed.

**Known Issues:**

- There are no known issues.

**Preceding Version:** F – 3.0



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VS-84HN  
**Preceding Version:** F – 3.0  
**Version Date:** December 2013  
**Reference:** 6542

The following changes were made in this version:

**Fixes:**

- Only certain combinations of inputs and outputs passed 7.1 audio.

**Known Issues:**

- There are no known issues.

**Preceding Version:** F – 2.3



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramerelect.com](mailto:info@kramerelect.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)