



Product Name: 860

Current Version:	Ver.Type	Ver No.	Date
	Firmware	2.07S	December 2016
	Software	–	–
	Web	–	–
	Hardware	–	–

RN Date: December 2016

Reference: 9384

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
860	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: 860

Current Version:

Ver.Type	Ver No.	Date
Firmware	2.07S	December 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 2016

Reference: 9384

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/downloads/860>

Bugs to be Fixed in Future Version:

QC ID	Description
9789	Cannot enter the SN to the product

Known Limitations (including compatibility limitations):

QC ID	Description
	None listed

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com