

## Release Notes

**Product Name:** DT-IN4-F32, DT-OUT4-F32

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	Input Card: 01.00.0009 Output Card: 01.00.0010	June 2018
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 2018

**Reference:** 12505

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
DT-IN4-F32	N/A	N/A	N/A
DT-OUT4-F32	N/A	N/A	N/A

### Technical Notes:

- This is a release note for new products.

### Codependency with Other Products and Software:

Product Name	Comments
VS-3232DN-EM	Modular matrix chassis



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** DT-IN4-F32, DT-OUT4-F32

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	Input Card: 01.00.0009 Output Card: 01.00.0010	June 2018
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 2018

**Reference:** 12505

This is a release note for new products. For a list of new product features see:

[https://k.kramerav.com/downloads/manuals/kramer\\_vs-3232dn-em.pdf](https://k.kramerav.com/downloads/manuals/kramer_vs-3232dn-em.pdf)

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)