

## Release Notes

**Product Name:** FC-102Net

**Current Version:**

Type	Number	Date
Firmware	1.1.51742	March 2019
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** March 7, 2019

**Reference:** 13513

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
FC-102Net	N/A	N/A	N/A

### Technical Notes:

- This is a release note for a new product.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** FC-102Net

**Current Version:**

Type	Number	Date
Firmware	1.1.51742	March 2019
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** March 7, 2019

**Reference:** 13513

This is a release note for a new product. For a list of new product features see:

[www.kramerav.com/manual/FC-102Net](http://www.kramerav.com/manual/FC-102Net)

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
13709	<p>After a performing a factory reset, the IP address on the Dante Controller is not aligned with the device IP.</p> <p><b>Workaround:</b> Reset the Dante Controller in one of the following ways:</p> <ul style="list-style-type: none"><li>• Reset the device through the Dante Controller.</li><li>• Disconnect the power source of the device – the RJ-45 connector.</li></ul>

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)