

## Release Notes

**Product Name:** VS-62D

**Current Version:**

Type	Number	Date
Firmware	1.6.63285	September 2023
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** September 5, 2023

**Reference:** 19130

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-62D	Any	Yes	Yes

### Summary:

- Updated Brand



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** VS-62D

**Current Version:**

Type	Number	Date
Firmware	1.6.63285	September 2023
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** September 5, 2023

**Reference:** 19130

### New Features:

	New Feature Description
	FW includes updated logo

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
9534	The device IP address didn't change after switching DHCP from on to off
9618	Product doesn't support reading of Valence FW version

**Preceding Version:** 1.5.37030



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-62D

**Current Version:**

Type	Number	Date
Firmware	1.5.37030	May 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** May 2017

**Reference:** 12376

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-62D	Any	Yes	N/A

### Technical Notes:

- Firmware for new Flash memory.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-62D

**Current Version:**

Type	Number	Date
Firmware	1.5.37030	May 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** May 2017

**Reference:** 12376

The following changes were made in this version:

### New Features:

	New Feature Description
	Firmware for new Flash memory

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
9534	The device IP address didn't change after switching DHCP from on to off
9618	Product doesn't support reading of Valence FW version

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** F - 1.5.32829



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-62DT

**Preceding Version:**

Type	Number	Date
Firmware	1.5.32829	December 2016
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** February 2016

**Reference:** 10060

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/downloads/VS-62DT>

### Bugs to be Fixed in Future Version:

QC ID	Description
9534	The device IP address didn't change after switching DHCP from on to off
9618	Product doesn't support reading of Valence FW version

### Known Limitations (including compatibility limitations):

QC ID	Description
	None listed

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)