



Product Name: RC-52A, RC-52N
Current Version: F – 16263
Version Date: February 2015
Reference: 8009, 8010

Release Type:

Firmware Software Hardware New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-52A	Any	No	Yes

Technical Notes:

- An IR command bug was fixed.

Codependency with Other Products and Software:

Product Name	Comments
K-Config	This FW version is compatible with K-Config 2.0.0.X and up. For devices running projects created with older versions of K-Config or RC-SV configurations, do not upgrade the FW.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com



Product Name: RC-52A, RC-52N
Current Version: F – 16263
Version Date: February 2015
Reference: 8009, 8010

The following changes were made in this version:

Fixes:

- An IR command bug was fixed.

Known Issues:

- There are no known issues.

Preceding Version: F - 5866



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: RC-52A, RC-52N

Preceding Version: F – 5866

Version Date: March 2014

Reference: 6824

The following changes were made in this version:

Added Features:

- This FW supports the updated “button behavior” options available in K-Config 2.0.0.X and up.

Fixes:

- Various bugs were fixed and performance stabilized.

Modifications:

- Speed enhancements were made.

Known Issues:

- There are no known issues.

Preceding Version: F - 3531



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com