

Release Note

Product Name: RC-76M

| Current Version: | Ver.Type | Ver No. | Date |
|-------------------------|----------|--------------|---------------|
| | Firmware | 4.0.43.42085 | December 2017 |
| | Software | – | – |
| | Web | – | – |
| | Hardware | – | – |

RN Date: December 2017

Reference: 12588

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| RC-76M | Any | Yes | N/A |
| | | | |

Codependency with Other Products and Software:

- There is no codependency with other products or software.

The following changes were made in this version:

Modifications:

| QC ID | Modification Description |
|-------|---|
| | Removed unused command descriptions from the Help |

Bugs Fixed:

| QC ID | Fixed Bug Description |
|-------|--|
| 10772 | The press event doesn't work when using Press-Release Functionality. |

Preceding Version: F – 4.0.33.29083

Release Note History

Product Name: RC-76M

Current Version:

| Ver.Type | Ver No. | Date |
|----------|--------------|-------------|
| Firmware | 4.0.33.29083 | August 2016 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: August 2016

Reference: 11005

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| RC-76R | Any | Yes | N/A |
| | | | |

Technical Notes:

- Support for new flash component.
- Improved PJLINK protocol handling.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Release Note History

Product Name: RC-76M

Current Version:

| Ver.Type | Ver No. | Date |
|----------|--------------|-------------|
| Firmware | 4.0.33.29083 | August 2016 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: August 2016

Reference: 11005

The following changes were made in this version:

New Features:

| | Description |
|--|-----------------------------------|
| | Support for new flash component |
| | Improved PJLINK protocol handling |

Bugs to be Fixed in Future Version:

| QC ID | Description |
|-------|-------------|
| | None listed |

Known Limitations (including compatibility limitations):

| QC ID | Description |
|-------|-------------|
| | None listed |

Preceding Version: F – 4.0.29.24637

Release Note History

Product Name: RC-76M
Current Version: F – 4.0.29.24637
Version Date: February 2016
Reference: 10061

The following changes were made in this version:

Modifications:

- Support for K-Config 3 features.

Known Issues:

There are no known issues.

Preceding Version: F – 4.0.15.11355

Release Note History

Product Name: RC-76M
Current Version: F – 4.0.15.11355
Version Date: January 2014
Reference: 6379

The following changes were made in this version:

Added Features:

Added support for K-Config 2 new relevant features:

- K-Config 2 – Support for new query mechanism
- K-Config 2 – Supports new tables
- K-Config 2 – Supports new DELAY
- K-Config 2 – Supports "Test command"
- K-Config 2 – Supports 10 Ethernet clients

Fixes:

- Various bugs were fixed and performance stabilized.

Modifications:

- Speed enhancements were made.

Known Issues:

- There are no known issues.

Preceding Version: F – 4.0.11.9835