

Release Notes

Product Name: TP-580RA

Current Version:

| Type | Number | Date |
|----------|------------|----------------|
| Firmware | R1.2.52352 | September 2020 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: September 29, 2020

Reference: 16729

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| TP-580RA | Any | Yes | Yes |

Technical Notes:

- Fixed a bug.
- Device has been tested with the latest versions of each of the following market popular browsers:

| | |
|---------|-----------|
| Windows | IE / Edge |
| | Firefox |
| | Chrome |
| Mac | Safari |

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: TP-580RA

Current Version:

| Type | Number | Date |
|----------|------------|----------------|
| Firmware | R1.2.52352 | September 2020 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: September 29, 2020

Reference: 16729

Bugs Fixed:

| QC ID | Fixed Bug Description |
|-------|---|
| 15319 | Rarely unstable output signal is experienced following long period of inactivity. |

Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description |
|-------|--|
| 12513 | Protocol 3000 CPEDID command does not support "safe mode" parameter. |

Known Limitations (including compatibility limitations):

| QC ID | Limitation Description |
|-------|---|
| 12079 | ARC audio de-embedding is supported only when CEC-enabled HDBT is connected |

Preceding Version: R1.2.43298



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: TP-580RA

Current Version:

| Type | Number | Date |
|----------|------------|---------------|
| Firmware | R1.2.43298 | November 2017 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: November 2017

Reference: 11304

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| TP-580RA | N/A | N/A | N/A |
| | | | |

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: TP-580RA

Current Version:

| Type | Number | Date |
|----------|------------|---------------|
| Firmware | R1.2.43298 | November 2017 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: November 2017

Reference: 11304

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/TP-580RA>

Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description |
|-------|--|
| 12513 | Protocol 3000 CPEDID command does not support "safe mode" parameter. |

Known Limitations (including compatibility limitations):

| QC ID | Limitation Description |
|-------|---|
| 12079 | ARC audio de-embedding is supported only when CEC-enabled HDBT is connected |

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com