

Release Note

Product Name: VP-772T

Current Version:	Ver.Type	Ver No.	Date
	Firmware	1.4	March 2018
	Software	–	–
	Web	–	–
	Hardware	–	–

RN Date: March 2018

Reference: 12007

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-772T	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

Product Name	Comments
VP-772	VP-772T is a remote control console that controls VP-772



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Note

Product Name: VP-772T

Current Version:	Ver.Type	Ver No.	Date
	Firmware	1.4	March 2018
	Software	–	–
	Web	–	–
	Hardware	–	–

RN Date: March 2018

Reference: 12007

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/VP-772T>

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
11808	Does not support auto discovery.
12189	When the IP address is changed, the web page freezes when performing factory reset from the web.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed.

Preceding Version: F – N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com