



Product Name: VP-796
Current Version: F – 1.7.42-2491
Version Date: March 2016
Reference: 10242

Release Type:

Firmware Software Hardware New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-796	No	Yes	N/A

Technical Notes:

- Various issues were added, fixed and modified.
- Detailed description of new features is in the updated User Manual available from our Web site

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-796
Current Version: F – 1.7.42-2491
Version Date: March 2016
Reference: 10242

The following changes were made in this version:

Added Features:

- Added a menu item to select between HDMI/DVI and DVI only on the DVI-U input.

Fixes:

- A chroma wrap issue was fixed.
- Switching interlaced input modes had a short drop down in the image.
- HDMI output with HDCP content was not re-established when sink goes into a power down mode with the hot plug line not being pulled at restart.
- Fixed issues with the device not being fully operational after an update without repowering the box once.

Modifications:

- The audio menu was reorganized.
- Network system improved. The network cable can now be pulled and re-plugged in live operation with the connection being re-established immediately.

Known Issues:

- There are no known issues.

Preceding Version: F – 1.4.21-2126



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-796
Preceding Version: F – 1.4.21-2126
Version Date: January 2016
Reference: 010003

The following changes were made in this version:

Added Features:

- Added 25Hz output modes.
- Added Display Port color control.
- Requester for Factory Reset after update was added.
- Added menu item under system/ input config/ test pattern setup to switch off tone coming along with test pattern.

Fixes:

- Fixed custom test pattern and logo upload.
- Bezel size now refers to display screen frame, not distance between screens.

Modifications:

- Re-activated PTZ Web browser control.

Known Issues:

- There are no known issues.

Preceding Version: NP – 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-796
Preceding Version: NP – 1.0
Version Date: December 2015
Reference: 7880

This is a release note for a new product.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com