



Product Name: RC-2C
Current Version: F – 26085
Version Date: March 2016
Reference: 9907

Release Type:

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-2C	Any	Yes	N/A

Technical Notes:

- An IR output problem was fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: RC-2C
Current Version: F – 26085
Version Date: March 2016
Reference: 9907

The following changes were made in this version:

Fixes:

- An IR output problem was fixed.

Known Issues:

- There are no known issues.

Preceding Version: F – 5866



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: RC-2C
Preceding Version: F – 5866
Version Date: March 2014
Reference: 6821

The following changes were made in this version:

Added Features:

- This FW supports the updated “button behavior” options available in K-Config 2.0.0.X and up.

Fixes:

- Various bugs were fixed and performance stabilized.

Modifications:

- Speed enhancements were made.

Known Issues:

- There are no known issues.

Preceding Version: F – 3531



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com



Preceding Version: F – 3531

Version Date: March 2011

Reference: 6600

The following changes were made in this version:

Modifications:

- The firmware was modified to support K-Config 1.0.1.X.

Known Issues:

- There are no known issues.

Preceding Firmware Version: 1962



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com