



**Product Name:** VP-796  
**Current Version:** F – 1.7.42-2491  
**Version Date:** March 2016  
**Reference:** 10242

**Release Type:**

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-796	No	Yes	N/A

**Technical Notes:**

- Various issues were added, fixed and modified.
- Detailed description of new features is in the updated User Manual available from our Web site

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerel.com](mailto:info@kramerel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VP-796  
**Current Version:** F – 1.7.42-2491  
**Version Date:** March 2016  
**Reference:** 10242

The following changes were made in this version:

## Added Features:

- Added a menu item to select between HDMI/DVI and DVI only on the DVI-U input.

## Fixes:

- A chroma wrap issue was fixed.
- Switching interlaced input modes had a short drop down in the image.
- Fix for missing audio on SDI input when switching from the CVBS/VGA/DVI/HMDI3/YPbPr group in a sequence with two channels of this group involved.
- HDMI output with HDCP content was not re-established when sink goes into a power down mode with the hot plug line not being pulled at restart.
- Fixed issues with the device not being fully operational after an update without repowering the box once.

## Modifications:

- The audio menu was reorganized.
- Network system improved. The network cable can now be pulled and re-plugged in live operation with the connection being re-established immediately.

## Known Issues:

- There are no known issues.

**Preceding Version:** F – 1.4.21-2126



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VP-796  
**Preceding Version:** F – 1.4.21-2126  
**Version Date:** January 2016  
**Reference:** 010003

The following changes were made in this version:

## **Added Features:**

- Added 25Hz output modes.
- Added Display Port color control.
- Requester for Factory Reset after update was added.
- Added menu item under system/ input config/ test pattern setup to switch off tone coming along with test pattern.

## **Fixes:**

- Fixed custom test pattern and logo upload.
- Bezel size now refers to display screen frame, not distance between screens.

## **Modifications:**

- Re-activated PTZ Web browser control.

## **Known Issues:**

- There are no known issues.

**Preceding Version:** NP – 1.0



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VP-796  
**Preceding Version:** NP – 1.0  
**Version Date:** December 2015  
**Reference:** 7880

This is a release note for a new product.

**Known Issues:**

- There are no known issues.

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerelect.com](mailto:info@kramerelect.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)