



Product Name: VP-440
Current Version: F – 1.07
Version Date: November 2015
Reference: 9570

Release Type:

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-440	Any	Yes	N/A

Technical Notes:

- Audio DSP features were added. A MacBook bug was fixed.

Codependency with Other Products and Software:

Product Name	Comments

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-440
Current Version: F – 1.07
Version Date: November 2015
Reference: 9570

The following changes were made in this version:

Added Features:

- Audio DSP features were added to increase MIC functionality
- Added TIMING SHIFT control to Web pages

Fixes:

- Fixed bug with MacBook exiting sleep mode

Known Issues:

- There are no known issues.

Preceding Version: NP – 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com



Product Name: VP-440
Preceding Version: NP – 1.0
Version Date: October 2015
Reference: 7631

This is a release note for a new product.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com